



NEW TRASDATA (JTAG/BDM/BOOT) ECU APPLICATION LIST

Release E/15 (19/10/2015) referred to SW: 3.0.148 DLL: 1.0.155 FW: 7.012 build 0001

DIMSPORT Srl Località San Iorio 8B, Zona Industriale Madonna 15020 Serralunga di Crea (AL) ITALY T +3901429552 F +390142940094

http://www.dimsport.it sales dept: info.race@dimsport.it; tech dept: support.race@dimsport.it

This application list is merely indicative. Dimsport Srl reserves the right to modify the list without any notice and at any time.

La presente lista ha carattere meramente indicativo. Dimsport Srl si riserva il diritto di apportare modifiche in qualunque momento e senza preavviso.

CPU SUPPORTED (GROUPS AND FAMILIES) / CPU SUPPORTATE (GRUPPI E SOTTOFAMIGLIE)

GROUP ID	CPU GROUP / GRUPPO CPU	CPU FAMILIES INCLUDED IN THE GROUP / FAMIGLIE CPU INCLUDE NEL GRUPPO
TF001	MOTOROLA MPC55X/MPC56X CPU group	-> 01 - MOTOROLA MPC55X/MPC56X (TM001)
TF002	STMICROELECTRONICS ST10 CPU group	-> 02 - STMICROELECTRONICS ST10 (TM002) -> 05 - SPECIAL ST10 (TM005)
TF003	INFINEON TRICORE CPU group	-> 03 - INFINEON TRICORE NO PSW (TM003) -> 04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004) -> 11 - INFINEON TRICORE SIEMENS SD16 PORSCHE (TM011) -> 12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012) -> 13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013) -> 14 - INFINEON TRICORE NO PSW KLINE (TM014) -> 15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015) -> 16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016) -> 18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018) -> 19 - INFINEON TRICORE BOSCH MEDC17 TPROT11 KIA/HYUNDAI -> 20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD -> 22 - INFINEON TRICORE BOSCH MEDC17 GPT BMW -> 23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG -> 24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO -> 25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR/LAND ROVER -> 26 - INFINEON TRICORE BOSCH MEDC17 GPT OPEL -> 27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES -> 28 - INFINEON TRICORE BOSCH MEDC17 GPT FORD -> 29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA -> 30 - INFINEON TRICORE BOSCH MEDC17 GPT MCLAREN -> 31 - INFINEON TRICORE BOSCH MEDC17 GPT RENAULT -> 32 - INFINEON TRICORE BOSCH MEDC17 GPT NISSAN -> 33 - INFINEON TRICORE BOSCH MEDC17 GPT ASTON MARTIN -> 34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA -> 35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA
TF004	MOTOROLA MPC55XX CPU group	-> 06 - NEXUS MOTOROLA MPC55XX (TM006)
TF005	RENESAS SH7050 CPU group	-> 07 - RENESAS SH7050 (TM007)
TF006	MITSUBISHI MH7xxx/MH8xxxx CPU group	-> 08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)
TF007	MOTOROLA MC68xxx CPU group	-> 09 - MOTOROLA MC68xxx (TM009)
TF008	MOTOROLA HC12 CPU group	-> 10 - MOTOROLA HC12 (TM010)
TF009	RENESAS M32R CPU group	-> 17 - RENESAS M32R (TM017)
TF010	NEC 76F00xx NBD CPU group	-> 36 - NEC NBD (TM017)

ECU SUPPORTED / CENTRALINE SUPPORTATE

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII	CHECKSUM MOD. / MOD. CHECKSUM
383	Agrale Cargo Truck	Bosch	EDC17C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
545	Agrale Cargo Truck	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
94	Aprilia / Piaggio	IAW Marelli	SDM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
239	Aprilia / Piaggio	IAW Marelli	7SM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
727	Aston Martin	Bosch	ME17.8.31	TC1797	TF003	33 - INFINEON TRICORE BOSCH MEDC17 GPT ASTON MARTIN		E94
424	Aston Martin	FoMoCo	PCM150x	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E117
721	Avia Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		NO CHECKSUM
613	Bentley	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E84
649	Bmc Cummins Engines	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
3	Bmw	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
100	Bmw	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
220	Bmw	Bosch	EDC17C41	TC1797	TF003	12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012)		E94
666	Bmw	Bosch	EDC17C41 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
221	Bmw	Bosch	EDC17C45	TC1797	TF003	12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012)		E94
670	Bmw	Bosch	EDC17C56	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
154	Bmw	Bosch	EDC17CP02	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
156	Bmw	Bosch	EDC17CP09 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
667	Bmw	Bosch	EDC17CP45 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
671	Bmw	Bosch	EDC17CP49	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
668	Bmw	Bosch	EDC17CP50/EDC17CP56 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH / SBLOCCO OBDDI	CHECKSUM MOD. / MOD. CHECKSUM
452	Bmw	Bosch	ME17.2 BMSX	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
604	Bmw	Bosch	ME7.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E19
19	Bmw	Bosch	ME9	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E75
229	Bmw	Bosch	ME9 2xDE28F800F3	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E75
103	Bmw	Bosch	ME9+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E75
163	Bmw	Bosch	ME9+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E75
679	Bmw	Bosch	MEDV17.2.5/MEDV17.2.8/MEDV17.2.9	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
171	Bmw	Bosch	MEV1746	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
215	Bmw	Bosch	MEV17.2	TC1787	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
678	Bmw	Bosch	MEDV17.2.G/MEDV17.2.6	TC1787	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
18	Bmw	Siemens	MS45.0	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E77
117	Bmw	Siemens	MSS 60 - MSS 65 #L	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E86
116	Bmw	Siemens	MSS 60 - MSS 65 #R	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E86
110	Bmw	Siemens	MSV70 / MSS70	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E78
65	Bmw / Mini	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
148	Bmw / Mini / PSA Group	Bosch	MED17.2/MEDV17.2 (ext. Flash)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
516	Bmw / Mini / PSA Group	Bosch	MEVD17.2.7	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
485	BMW / Yanmar	Bosch	EDC16C1-4.41	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
136	Bmw Bikes	Bosch	ME9 BMSK	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E95
188	Bmw Bikes	Bosch	ME9+ BMSK	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E75/E95
552	Brp	Continental Siemens VDO	M3C S12XET256MAL	MC9512XS256	TF008	10 - MOTOROLA HC12 (TM010)		E115
536	Bugatti	Bosch	ME9.1.1	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E141
124	Case (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
467	Case / New Holland	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94/E145
392	Caterham	MBE	958	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
704	Caterpillar	CAT	A5M8	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		
440	Caterpillar	Caterpillar	Adem III (AT25160 eeprom)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
385	Caterpillar	Caterpillar	Adem III (AT25640 eeprom)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
648	Caterpillar	Caterpillar	Adem III (HWIII)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
332	Caterpillar	Caterpillar	Adem IV (561/562)	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
360	Caterpillar	Caterpillar	Adem IV (563/564 S29CD016G)	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
408	Caterpillar	Caterpillar	Adem IV (563/564 S29CD032I)	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
161	Caterpillar	Delphi	Perkins	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
323	CF Motor	Bosch	MSE3	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E122
409	Chery	Bosch	ME7.9.7	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
429	Chery	IAW Marelli	IAW44C	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
576	Chery	Siemens	SIMK31	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
17	Chevrolet / GM Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
74	Chevrolet / GM Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
660	Chevrolet / GM Group	Bosch	EDC16C39	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
519	Chevrolet / GM Group	Bosch	EDC16C42	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
309	Chevrolet / GM Group	Bosch	ME9.1 / ME9.5	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E105
202	Chevrolet / GM Group	Continental	SIM2K	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E111
224	Chevrolet / GM Group / FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.9	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E114
465	Chevrolet / GM Group / Opel	Delco	E83	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E135
14	Chrysler / Jeep	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
106	Chrysler / Jeep	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
503	Chrysler / Jeep	Bosch	EDC17C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAI (TM015)		E94
371	Chrysler / Jeep	Motorola	NC64	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E139
372	Chrysler / Jeep	Motorola	NC65	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E139
193	Cummins engines (generic)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
406	Cummins engines (Tractor generic)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
546	Cummins engines (Truck generic)	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		NO CHECKSUM
565	Cummins engines (Truck generic)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
582	Dacia	Siemens Continental	EMS3130	ST10F273	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E83
619	Daewoo	Siemens	D42	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
361	Daewoo / Opel GM Group	Siemens	M300 B10D	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
134	Daf Truck	Bosch	EDC7C-C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
506	Daf Truck	Continental	CM2150C	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		NO CHECKSUM
403	Daf Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		NO CHECKSUM
142	Daf Truck	Delphi	DCM1	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E76
125	Daf Truck	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
509	Daf Truck (Paccar Engine)	Delphi	PCX2	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E138
742	Daimler Truck (Cummins Engine)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
639	Daimler Trucks	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		NO CHECKSUM
543	Detroit Diesel Trucks	Teric	ACM2	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
627	Detroit Diesel Trucks	Teric	ACM2 - AT25256	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
144	Deutz / Fendt (AGCO Group)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
227	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
577	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
436	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV56	ST10C167	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
160	Deutz / Fendt (AGCO Group)	Bosch	EDC17U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
80	Dodge	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
95	Dodge	Motorola	CM848B	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
641	Dodge	Motorola	NC65	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E139
473	Dodge	Siemens	SIM90T	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E110
566	Dodge (Cummins Engine)	Motorola	CM848E/CM849B	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
635	Doosan	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
718	Ducati	Continental	M3D	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E115
341	Ducati	Continental Siemens VDO	M3C S12X256SV	MC9512XS256	TF008	10 - MOTOROLA HC12 (TM010)		E115
540	Ducati	Continental Siemens VDO	M3C S12XET256MAL	MC9512XS256	TF008	10 - MOTOROLA HC12 (TM010)		E115
653	Ducati	Melco	HIMEII	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
87	Ducati / MV Agusta	IAW Marelli	SSM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
394	Duramax	Bosch	EDC17CP18	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
1	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
70	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
141	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
503	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAI (TM015)		E94

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII	CHECKSUM MOD. / MOD. CHECKSUM
655	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C69	TC1793	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11_FAL (TM015)		E94
733	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C69	TC1793	TF003	29 - INFINEON TRICORE BOSCH MEDC17_GPT_FCA		E94
363	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17CP52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
659	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.3.0	TC1724	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
24	FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.10	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E94
642	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.3.0	TC1724	TF003	15 - INFINEON TRICORE BOSCH EDC17_TPROT11_FAL (TM015)		E91
150	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.3.1	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
643	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.3.3	TC1793	TF003	15 - INFINEON TRICORE BOSCH EDC17_TPROT11_FAL (TM015)		E94
643	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E99
30	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E91
27	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.6.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E91
26	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.6.2	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E93
515	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4AF.P2	ST10F168	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
380	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4CF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
381	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4GF	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
44	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4SF / 4DF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
63	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	5SF8 / 5SF9	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
28	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	5SFHxxxx	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
91	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	6KPB	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E74
247	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	7GF	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E101
645	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8DF.I1	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E101
382	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8F3	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E101
245	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GF	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E101
243	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GMF	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E101
413	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8TDF	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E101
85	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
101	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
349	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3 HW04W	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
8	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6FJ	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
303	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 8DF	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E101
83	FCA (Fiat/Chrysler Automobiles)	Siemens	SID 803A 5WS40320	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
38	FCA (Fiat/Chrysler Automobiles) / PSA Group	Visteon	DCU-102	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E92
366	Fendt (AGCO Group)	Agco	Gearbox	ST10F269	TF002	05 - SPECIAL ST10 (TM005)		NO CHECKSUM
335	Ferrari	Bosch	ME9.6.1	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E113
42	Ferrari / Maserati	Bosch	ME7.3.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E89
121	Ford	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
230	Ford	Bosch	EDC17C10	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
698	Ford	Bosch	EDC17C10	TC1797	TF003	28 - INFINEON TRICORE BOSCH MEDC17_GPT_FORD		E94
197	Ford	Bosch	EDC17CP05	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
737	Ford	Bosch	EDC17CP05	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
301	Ford	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
76	Ford	Bosch	ME8+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E70
586	Ford	Bosch	ME17.2	TC1767	TF003	20 - INFINEON TRICORE BOSCH MEDC17_TPROT12_FORD		E94
618	Ford	Bosch	ME17.2.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
200	Ford	Bosch	ME17.8.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
279	Ford	Bosch	MEDG9.8	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E117
233	Ford	Delphi	DCM	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E62
302	Ford	Delphi	DCM3.5	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E100
343	Ford	FoMoCo	JDS0	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E117
464	Ford	IAW Marelli	4AFR	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
393	Ford	IAW Marelli	4CF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
663	Ford	Siemens	EMS2205	TC1762 / TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
145	Ford	Siemens	SID 206 5WS40483	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
460	Ford	Siemens	SID901	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E47
577	Ford	Siemens	SID902	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
749	Ford	Siemens Continental	EMS2204/2207/2211	TC1738	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)		E83
511	Ford	Siemens Continental	SID807EVO	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	Patch (OBDDII Unlock)	E83
178	Ford	Siemens/Continental	SID807	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
20	Ford / Jaguar	Delphi	MPC555 / MPC556	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E62
510	Ford / Land Rover	FoMoCo Continental	SID208	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	Patch (OBDDII Unlock)	E137
11	Ford / Mazda	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
60	Ford / PSA Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
66	Ford / PSA Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
32	Ford / PSA Group / Volvo	Siemens	SID 803 5WS40xxx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
78	Ford / PSA Group / Volvo	Siemens	SID 803A 5WS40xxx	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
238	Ford / Volvo	Bosch	ME17.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
82	Ford / Volvo	Siemens	SID 206 5WS40xxx	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
31	Ford Truck	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
504	Ford Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		NO CHECKSUM
461	Freightliner / Mercedes Truck	Teric	DDEC6	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
684	Geely	Delphi	MT80	TC1762 / TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
614	Generic Car/LCV	Bosch	EDC17CV42	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
595	Generic Tractor	Recon	CM554	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
615	Generic Truck	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94/E145
632	Generic Truck (Cummins Engine)	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		NO CHECKSUM
7	GM Group / Opel	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
228	GM Group / Opel	Bosch	EDC17C18	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
153	GM Group / Opel	Bosch	EDC17C19	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17_TPROT2/4/7 (TM004)		E94
688	GM Group / Opel	Bosch	EDC17C59	TC1767	TF003	26 - INFINEON TRICORE BOSCH MEDC17_GPT_OPEL		E94
717	GM Group / Opel	Bosch	EDC17CP47	TC1797	TF003	26 - INFINEON TRICORE BOSCH MEDC17_GPT_OPEL		E94
192	GM Group / Opel	Bosch	ME7.6.4	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E105
225	GM Group / Opel	Bosch	ME9.6	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E105
466	GM Group / Opel	Delco	E37	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E135
520	GM Group / Opel	Delphi	SH2544R	SH2544R	TF005	07 - RENESAS SH7050 (TM007)		E100
605	GM Group / Opel	Delphi	DCM 3.7AP	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E100
706	GM Group / Opel	Denso	94661024	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
253	GM Group / Opel	Denso	1.7 DTI	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
295	GM Group / Opel	Denso	1.7 DTI SH7059	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
10	GM Group / Opel	IAW Marelli	MJD 6FJ	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH / SBLOCCO OBDDI	CHECKSUM MOD. / MOD. CHECKSUM
111	GM Group / Opel	JAW Marelli	MJD 602.A6	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
107	GM Group / Opel	JAW Marelli	MJD 602.M1 - MJD 603.S3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
176	GM Group / Opel	JAW Marelli	MJD 602.M1 - MJD 603.S3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
333	GM Group / Opel	Siemens	SIMTEC 76	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
309	GM Group / Opel / Chevrolet	Bosch	ME9.1 / ME9.5	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E105
465	GM Group / Opel / Chevrolet	Delco	E83	MPC565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E135
458	GM Group / Opel / Chevrolet	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH7050 (TM007)		E100
329	GM Group / Opel / Isuzu	Denso	3.0 V6 DTI	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
348	GM Group / Opel / Suzuki	JAW Marelli	MJD 602.04	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
84	Great Wall Motor	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
470	Great Wall Motor	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
439	Great Wall Motor	Bosch	ME7.8.8	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E127
388	Great Wall Motor	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH7050 (TM007)		E100
487	Hino	Denso	895xx	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
347	Hino	Denso	896xx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
12	Honda	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
731	Honda	Bosch	EDC17C58	TC1793	TF003	35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA		E94
172	Honda	Bosch	EDC17CP06	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
213	Honda	Bosch	EDC17CP16	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
497	Honda	Bosch	ME7.9.3	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
730	Honda	Keihin	37805-Pxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
492	Honda	Keihin	37805-Rxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
617	Honda	Keihin	37820-RAH	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
61	Hyundai / Kia	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
72	Hyundai / Kia	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
164	Hyundai / Kia	Bosch	EDC17C08	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
608	Hyundai / Kia	Bosch	EDC17C53	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
682	Hyundai / Kia	Bosch	EDC17C57	TC1793	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
127	Hyundai / Kia	Bosch	EDC17CP14	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
549	Hyundai / Kia	Bosch	EDC17CP14	TC1796	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
683	Hyundai / Kia	Bosch	M7.9	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E14
167	Hyundai / Kia	Bosch	M7.9.8	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E106
339	Hyundai / Kia	Bosch	ME17.9.11	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
597	Hyundai / Kia	Bosch	ME7.9.7	ST10F275	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
496	Hyundai / Kia	Bosch	MED17.9.8	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
550	Hyundai / Kia	Bosch	MED17.9.8/MEDG17.9.8	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
416	Hyundai / Kia	Bosch	MEG17.9.11	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
693	Hyundai / Kia	Bosch	MEG17.9.2	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
194	Hyundai / Kia	Continental	SIM2K	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E111
387	Hyundai / Kia	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH7050 (TM007)		E100
317	Hyundai / Kia	Kefico	EHB	MH8305H	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
351	Hyundai / Kia	Kefico	KTS3	MH8X02F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
575	Hyundai / Kia	Mitsubishi	39106-3945x	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
367	Hyundai / Kia	Siemens	SIM2K-47 SWY4Cxxx #L	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
368	Hyundai / Kia	Siemens	SIM2K-47 SWY4Cxxx #R	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
352	Hyundai / Kia	Siemens	SIMK43 SWY1xxxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
353	Hyundai / Kia	Siemens	SIMK43 SWY44xxx #L	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
354	Hyundai / Kia	Siemens	SIMK43 SWY44xxx #R	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
521	Hyundai / Kia	Siemens Continental	SIM2K	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E111
169	Hyundai / Kia (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
112	Hyundai / Kia / Ssangyong	Delphi	DCM3.2	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E81
623	Hyundai Trago	Delphi	ETC3	MPC556	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E138
621	International Truck	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
400	International Truck (Cummins)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
401	International Truck (Cummins)	Motorola	CM871 / CM876	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
745	Isuzu	Bosch	EDC17CV41	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
412	Isuzu	Denso	25841077	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
430	Isuzu	Transtron	4Jxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
490	Isuzu	Transtron	Transtron	SH72544R	TF005	07 - RENESAS SH7050 (TM007)		E121
703	Isuzu	Transtron	Transtron SH7059	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
313	Isuzu	Transtron	Transtron	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
79	Isuzu / Chevrolet	Delphi		MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E82
322	Isuzu / GM Group / Opel	Denso	3.0 V6 DTI	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
579	Isuzu Giga	Denso	895xx	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
130	Iveco	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
140	Iveco	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
206	Iveco	Bosch	EDC17	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
432	Iveco	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
633	Iveco	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E145
568	Iveco	JAW Marelli	IAW 55F4	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
129	Iveco / New Holland	Bosch	EDC7C1-C2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E63
137	Iveco / New Holland	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67/E133
346	Jaguar	Denso	MB079700	SH7055	TF005	07 - RENESAS SH7050 (TM007)		NO CHECKSUM
422	Jaguar	Denso	MB279700-9xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
105	Jaguar	Siemens	SID 201 - SID 204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
685	Jaguar / Land Rover	Bosch	MED17.8.31	TC1797	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR		E94
498	Jaguar / Land Rover	Denso	P5.OSC	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
593	JCB	Continental	CM2250	MPC556	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		NO CHECKSUM
701	JCB	Delphi	DCM3.3	SH72544R	TF005	07 - RENESAS SH7050 (TM007)		E100
402	JCB / Massey Ferguson	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
191	JCB Fastrack	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
598	Jeep	Bosch	EDC17C79	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
256	Jeep	Bosch	EDC17CP27	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
503	Jeep / Chrysler / FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
77	Jeep / Mitsubishi	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
190	John Deere	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
462	John Deere	Phoenix	L11	ST10F168	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
123	John Deere	Phoenix	L14	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E104

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH / SBLOCCO OBDDI	CHECKSUM MOD. / MOD. CHECKSUM
236	John Deere	Phoenix	L16	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
463	John Deere	Phoenix	L4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
508	John Deere	Phoenix	L9/L11	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
457	John Deere	Siemens	UIC2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
525	Kawasaki	Denso	21175-0220	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
687	Kawasaki	Denso	21175-03XX	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
652	Kawasaki	Denso	21175-08XX	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
532	Kawasaki	Denso	21175-0045	SH7054	TF005	07 - RENESAS SH7050		E121
532	Kawasaki	Denso	21175-0097	SH7054	TF005	07 - RENESAS SH7050		E121
620	Kawasaki	Denso	21175-07XX	SH7054	TF005	07 - RENESAS SH7050		E121
561	Kawasaki	Denso	21175-109X	SH7054	TF005	07 - RENESAS SH7050		E121
530	Kawasaki	Melco	21175-3732	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
455	Kawasaki	Melco	ULTRA 300x	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
637	Kawasaki	Mitsubishi	21175-033X	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx		E121
625	Kawasaki	Mitsubishi	21175-076X	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx		E121
285	Kawasaki	Mitsubishi	JetSki Ultra 250	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
300	Kawasaki	Mitsubishi	ZRX1200	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
484	Kawasaki	Mitsubishi	ZX10R	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx		E121
488	Kawasaki	Mitsubishi	ZX10R MY07	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx		E121
744	Kenworth Truck (Cummins Engine)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
541	Khodro/Saipia	Continental	SIM2K-34 5WY5Kxxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
379	King Long	Continental	CM2150E	MPC566	TF004	06 - NEXUS MOTOROLA MPC55X (TM006)		NO CHECKSUM
438	Komatsu	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
418	Ktm	Bosch	M17.8.7	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
584	Kubota	Denso	275700-1201	SH7058	TF005	07 - RENESAS SH7050		E121
578	Kubota	Denso	275800-7221	SH7058	TF005	07 - RENESAS SH7050		E121
376	Lada / UAZ	Bosch	M7.9.7	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
428	Lada / UAZ	Bosch	ME17.9.7	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
469	Lamborghini	Campl	MC68300	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
120	Land Rover	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
177	Land Rover	Bosch	EDC17CP11	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
235	Land Rover	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
483	Land Rover	Denso	MB279700-94xx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
98	Land Rover	Siemens	SID 201 - SID 204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
115	Land Rover	Siemens	SID 203 5WS40371	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
384	Land Rover	Siemens	SID 204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
37	Land Rover	Visteon	DCU-106	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E92
510	Land Rover / Ford	FoMoCo Continental	SID208	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)		E137
498	Land Rover / Jaguar	Bosch	P5.OSC	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
310	LDV	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
567	Lindner Perkins	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
287	Lotus	Efi	Efi	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
306	Lotus	Efi	Efi	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
437	Lotus	Efi	T4E	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E129
507	Lotus	Efi	T6E	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55X (TM006)		E129
447	LTI	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
453	Mack	Bosch	EDC7U/U1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E130
21	Mahindra	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
699	Mahindra	Bosch	EDC16 C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
558	Mahindra	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
495	Mahindra	Bosch	EDC17C55	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
538	Man Latin America / Volkswagen Trucks	Continental	CM2150E	MPC556	TF004	06 - NEXUS MOTOROLA MPC55X (TM006)		NO CHECKSUM
135	Man Truck	Bosch	EDC7C3	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E66
139	Man Truck	Bosch	EDC7C32	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
596	Maserati	Bosch	EDC17C79	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
226	Maserati	Bosch	ME911	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E113
711	Maserati	Bosch	MED17.3.4	TC1797	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
402	Massey Ferguson / JCB	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
270	Massey Ferguson / McCormick / Caterpillar	Perkins	Caterpillar Tier2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
651	Maz Trucks	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
395	Mazda	Denso	N311	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
263	Mazda	Denso	R2AX	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
278	Mazda	Denso	RF7K	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
476	Mazda	Denso	L374	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
518	Mazda	Denso	L37A	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
321	Mazda	Denso	L831	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
327	Mazda	Denso	R2AA	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
277	Mazda	Denso	RF8G	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
344	Mazda	Denso	SH7058	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
454	Mazda	Denso	ZYF9	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
517	Mazda	Mitsubishi	E6T540xxxx	MH8105F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
603	Mazda	Mitsubishi	E6T58xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
373	Mazda	Mitsubishi	E6T5x	MH8105F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
475	Mazda	Mitsubishi	FPV1EA	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
345	Mazda	Mitsubishi	L3B1	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
708	McLaren	Bosch	MED17.8.3	TC1797	TF003	30 - INFINEON TRICORE BOSCH MEDC17 GPT MCLAREN		E94
4	Mercedes	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
71	Mercedes	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
97	Mercedes	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
114	Mercedes	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
222	Mercedes	Bosch	EDC17C01	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
231	Mercedes	Bosch	EDC17C43	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
700	Mercedes	Bosch	EDC17C57	TC1793	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
710	Mercedes	Bosch	EDC17C66	TC1793	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
157	Mercedes	Bosch	EDC17CP01	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
155	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
182	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
273	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH / SBLOCCO OBDDI	CHECKSUM MOD. / MOD. CHECKSUM
365	Mercedes	Bosch	EDC17CP46	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
691	Mercedes	Bosch	EDC17CP46	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
622	Mercedes	Bosch	ME2.8	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E16
102	Mercedes	Bosch	ME9.7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E79
204	Mercedes	Bosch	ME9.7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E79
692	Mercedes	Bosch	ME017.7.2	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
249	Mercedes	Bosch	ME017.1	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
514	Mercedes	Bosch	ME017.7.8	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
248	Mercedes	Delphi	CR02.10	MPC556	TF004	06 - NEXUS MOTOROLA MPC55X (TM006)		E100
119	Mercedes	Delphi	DCM3.2	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E81
580	Mercedes	Siemens	EGS52	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E146
581	Mercedes	Siemens	EGS53	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E146
175	Mercedes	Siemens	SIM 266	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E124
500	Mercedes	Siemens	SIM 266 (ex flash S29CD032)	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E124
542	Mercedes Truck	Continental	HDEP	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
628	Mercedes Truck	Continental	HDEP MCM2.1	TC1797	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
461	Mercedes Truck / Freightliner	Teric	DDEC6	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
189	Mercury Marine	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
33	Mercury Marine	Motorola	ECM04xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E119
442	Mercury Marine	Motorola	ECM0501	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E119
90	Mercury Marine	Motorola	ECM070xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E119
132	Mercury Marine	Motorola	ECM555	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E119
36	Mercury Marine	Motorola	PCM0308	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E119
35	Mercury Marine	Motorola	PCM0702	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E119
441	Mercury Marine	Motorola	PCM08xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E119
34	Mercury Marine	Motorola	PCMBE0101	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E119
419	MG	Bosch	ME7.9.71	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
152	Mini	Bosch	MED172/MEV172 (irom)	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
237	Mini	Bosch	MEV17.2.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
208	Mini	Bosch	MEVD17.2.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
719	Mini	Bosch	MEVD17.2.3	TC1793	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW		E94
43	Mitsubishi	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
640	Mitsubishi	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
170	Mitsubishi	Bosch	EDC17CP15 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
588	Mitsubishi	Bosch	EDC17CP52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
573	Mitsubishi	Bosch	ME7.7.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E144
265	Mitsubishi	Denso	(4D56 engine)	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
601	Mitsubishi	Denso	6M60	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
629	Mitsubishi	Denso	6M60	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
263	Mitsubishi	Denso	EV0X	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
319	Mitsubishi	Denso	RA6	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
417	Mitsubishi	Denso	RA6 4D56	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
324	Mitsubishi	Denso	RA6 4N13	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
232	Mitsubishi	IAW Marelli	4AM	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
337	Mitsubishi	IAW Marelli	4CM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
444	Mitsubishi	IAW Marelli	4DM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
423	Mitsubishi	IAW Marelli	4GM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
589	Mitsubishi	IAW Marelli	4GT	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
548	Mitsubishi	IAW Marelli	IAW4DM CR47	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
350	Mitsubishi	Melco	G1Tx	MH8X02F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
318	Mitsubishi	Mitsubishi	3.2 D	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
570	Mitsubishi	Mitsubishi	E2711xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
609	Mitsubishi	Mitsubishi	E2799xxx	MH8306F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
449	Mitsubishi	Mitsubishi	E277xxx MH7203	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
479	Mitsubishi	Mitsubishi	E6T310xx	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
493	Mitsubishi	Mitsubishi	E6T310xx	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
585	Mitsubishi	Mitsubishi	E6T36xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
474	Mitsubishi	Mitsubishi	E6T38xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
482	Mitsubishi	Mitsubishi	E6T41xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
602	Mitsubishi	Mitsubishi	E6T44xxx	MH8304F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
410	Mitsubishi	Mitsubishi	E6T47xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
391	Mitsubishi	Mitsubishi	E6T49xxx	MH8304F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
583	Mitsubishi	Mitsubishi	E6T74xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
426	Mitsubishi	Mitsubishi	E6T76xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
328	Mitsubishi	Mitsubishi	E6T7x	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
329	Mitsubishi (Colt 1.5 asp.)	Mitsubishi	MH7x/MH8x	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
255	Mitsubishi (Colt 1.5 turbo)	Mitsubishi	MH7x/MH8x	MH8203F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
261	Mitsubishi (Lancer EVO IX)	Mitsubishi	MH7x/MH8x	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
259	Mitsubishi (Lancer EVO VI)	Mitsubishi	MH7x/MH8x	MH7202F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
260	Mitsubishi (Lancer EVO VII/VIII)	Mitsubishi	MH7x/MH8x	MH7202F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
297	Mitsubishi (Pajero 3.2 DI-D)	Mitsubishi	MH7x/MH8x	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
99	Mitsubishi / Smart	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
547	Moto Guzzi	IAW Marelli	IAW75M	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
217	HV Augusta	IAW Marelli	7BM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
143	New Holland	Bosch	EDC16+ C39/UC40	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
467	New Holland / Case	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94/E145
129	New Holland / Iveco	Bosch	EDC7C1-C2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E63
137	New Holland / Iveco	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67/E133
478	Nissan	Bosch	EDC16CP42	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
657	Nissan	Bosch	EDC17C45	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
724	Nissan	Bosch	EDC17C84	TC1782	TF003	32 - INFINEON TRICORE BOSCH MEDC17 GPT NISSAN		E94
294	Nissan	Denso	1H	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
264	Nissan	Denso	D3	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
314	Nissan	Denso	HP	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
315	Nissan	Denso	HWII	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
647	Nissan	Hitachi	23710-5Y222	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
445	Nissan	Hitachi	A56-B7x	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
450	Nissan	Hitachi	A56-C1x	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH / SBLOCCO OBDDI	CHECKSUM MOD. / MOD. CHECKSUM
661	Nissan	Hitachi	A56-U45	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
481	Nissan	Hitachi	BED301-000	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
448	Nissan	Hitachi	DEA030-2xx	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
296	Nissan	Hitachi	HPNGV	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
396	Nissan	Hitachi	HPNGV SH7059	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
298	Nissan	Hitachi	HW 1	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
299	Nissan	Hitachi	HW 4	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
502	Nissan	Hitachi	MEC-100-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
414	Nissan	Hitachi	MEC-107	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
494	Nissan	Hitachi	MEC-23-xxx	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
451	Nissan	Hitachi	MEC-30-07x	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
600	Nissan	Hitachi	MEC-35	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
650	Nissan	Hitachi	MEC-37-3xx	SH7054	TF005	07 - RENESAS SH7050 (TM007)		E121
680	Nissan	Hitachi	MEC-37-900	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
694	Nissan	Hitachi	MEC-38-310	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
415	Nissan	Hitachi	MEC-73-xxx	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
606	Nissan	Hitachi	MEC-78-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
501	Nissan	Hitachi	MEC-90-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
587	Nissan	Hitachi	MEC-940-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
486	Nissan Truck (Cummins engine)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
431	Peterbilt Truck (Cummins engine)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
377	Piaggio	Bosch	EDC17C08	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
307	Polaris	Bosch	M17.8.7	TC1762	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
673	Polaris	Bosch	M17.9.74	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
56	Polaris	Bosch	M7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
57	Polaris	Bosch	ME7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
282	Polaris	Bosch	ME7.9.7	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
240	Porsche	Bosch	ME7.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
242	Porsche	Bosch	ME7.8	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
41	Porsche	Bosch	ME7.8.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
40	Porsche	Bosch	ME7.8.2	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E87
159	Porsche	Bosch	ME7.8.2 min	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E87
39	Porsche	Siemens/Continental	VDO SD13/SD14	TC1796	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E96
272	Porsche	Siemens/Continental	VDO SD16	TC1796	TF003	11 - INFINEON TRICORE SIEMENS SD16 PORSCHE (TM011)		E96
108	Porsche / VAG (VW Group)	Bosch	MED9.1 FS1 - MED9.1.1 FS1	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E58/E85/E123
534	Proton	Siemens VDO	PW5XX	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E140
535	Proton	Siemens VDO	PW8XX	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E140
5	PSA Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
118	PSA Group	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
728	PSA Group	Bosch	EDC17 C60	TC1793	TF003	04 - INFINEON TRICORE BOSCH MEDC17 GPT PSA		E94
198	PSA Group	Bosch	EDC17 CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
219	PSA Group	Bosch	EDC17C10	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
312	PSA Group	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
551	PSA Group	Bosch	M7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
397	PSA Group	Bosch	ME7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
25	PSA Group	Bosch	ME7.4.5	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E88
569	PSA Group	Bosch	ME7.4.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
47	PSA Group	Bosch	ME7.4.9	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E88
729	PSA Group	Bosch	MED17.4.4	TC1793	TF003	04 - INFINEON TRICORE BOSCH MEDC17 GPT PSA		E94
196	PSA Group	Bosch	MED17.4/MEV17.4	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
305	PSA Group	Bosch	MED17.4/MEV17.4 (Irom)	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
209	PSA Group	Bosch	MED17.4/MEV17.4 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
286	PSA Group	Bosch	MEV17.4.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
216	PSA Group	Bosch	MEVD17.4.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
741	PSA Group	Bosch	MEVD17.4.4	TC1793	TF003	04 - INFINEON TRICORE BOSCH MEDC17 GPT PSA		E94
257	PSA Group	Delphi	DCM3.4	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E100
362	PSA Group	Delphi	DCM3.4	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E100
244	PSA Group	Delphi	DCM3.5	MPC556	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E100
55	PSA Group	Delphi	DDCR	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E100
45	PSA Group	IAW Marelli	6LP1.49	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E74
46	PSA Group	IAW Marelli	6LPC.102	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E74
599	PSA Group	Siemens	S2000	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E60
104	PSA Group	Siemens	SID 201 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E68
443	PSA Group	Siemens	SID 801	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E26
320	PSA Group	Siemens/Continental	SID 807 (Irom)	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
359	PSA Group	Siemens/Continental	SID 807 (xrom)	TC1796	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
122	PSA Group	Valeo Johnson	J34P	ST10F273	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E103
211	PSA Group	Valeo Johnson	J34P	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E103
491	PSA Group	Valeo Johnson	J34P HW II	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E103
6	Renault Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
133	Renault Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
29	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
62	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
69	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
223	Renault Group	Bosch	EDC16C36	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
234	Renault Group	Bosch	EDC16CP33	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
201	Renault Group	Bosch	EDC17C11	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
181	Renault Group	Bosch	EDC17CP19	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
456	Renault Group	Bosch	EDC17CP58	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
720	Renault Group	Bosch	ME7.4.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
709	Renault Group	Bosch	MED17.9.20	TC1782	TF003	31 - INFINEON TRICORE BOSCH MEDC17 GPT RENAULT		E94
258	Renault Group	Delphi	DCM3.4	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E100
529	Renault Group	Hitachi	A56-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
531	Renault Group	Hitachi	MEC121-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
571	Renault Group	Hitachi	MEC800	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
88	Renault Group	Sagem	S2000RPM	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E60
250	Renault Group	Sagem	S3000	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E73
210	Renault Group	Siemens	EMS3110	TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII	CHECKSUM MOD. / MOD. CHECKSUM
81	Renault Group	Siemens	SID 301	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E83
205	Renault Group	Siemens	SID 305	TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
252	Renault Group	Siemens	SIM32	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E73
336	Renault Group	Siemens	SIRIUS 32	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E25
471	Renault Group	Siemens	SIRIUS 34	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E28
280	Renault Group	Valeo	S3000	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E73
251	Renault Group	Valeo	V40	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E73
308	Renault Group / Nissan	Bosch	EDC17C42	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
292	Renault Group / Samsung	Hitachi	DA A56-Y8x	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
138	Renault Truck / Volvo Truck	TRW	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E80
330	Rotax	Siemens VDO	MSE 3.7	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E126
411	Rotax	Siemens VDO	MSE 3.7 R/H3	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E126
180	Rotax (Sea Doo Acqua Scooter)	Bosch	ME17.8.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
654	Same	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
590	Scania Truck	Continental	EMS 57	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E64
594	Scania Truck	Continental	EMS 58	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E64
131	Scania Truck	Motorola	FDCS6	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E64
738	Sinotruck	Bosch	EDC17CV44	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
23	Smart	Bosch	ME7.7.0	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E90
480	Smart	Mitsubishi	G2T601x Gearbox	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx		E121
459	Ssangyong	Delphi	SH72513	SH72513	TF005	07 - RENESAS SH7050 (TM007)		E100
524	Ssangyong	Delphi	DCM 3.7	SH72544R	TF005	07 - RENESAS SH7050 (TM007)		E100
22	Ssangyong	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E65
564	Subaru	Denso	112200-8481	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
630	Subaru	Denso	112300-0430	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
281	Subaru	Denso	CJ	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
375	Subaru	Denso	DM	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
276	Subaru	Denso	DT	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
275	Subaru	Denso	KS	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
644	Subaru	Hitachi	DEF002-XXX	SH7059	TF005	07 - RENESAS SH7050 (TM007)		E121
16	Suzuki	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
212	Suzuki	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
446	Suzuki	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
340	Suzuki	Bosch	ME17.8.XX	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
434	Suzuki	Bosch	ME17.8.XX	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
370	Suzuki	Denso	057L1	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
331	Suzuki	Denso	0763x	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
262	Suzuki	Denso	1.3 MT	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E121
316	Suzuki	Denso	1.6 MT	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
533	Suzuki	Denso	32920-01H000	SH7054	TF005	07 - RENESAS SH7050 (TM007)		E121
528	Suzuki	Denso	32920-08J11	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
523	Suzuki	Denso	32920-21Hxxx	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
672	Suzuki	Denso	32920-24FXx	SH7054	TF005	07 - RENESAS SH7050 (TM007)		E121
526	Suzuki	Denso	32920-30G00	SH7054	TF005	07 - RENESAS SH7050 (TM007)		E121
557	Suzuki	Denso	3C3/2C0-8591A-XX	SH7054	TF005	07 - RENESAS SH7050 (TM007)		E121
364	Suzuki	IAW Marelli	BDS	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E101
9	Suzuki	IAW Marelli	IJZ13DT	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
616	Suzuki	Mitsubishi	33920-93J40	MH5xxxF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
489	Suzuki	Mitsubishi	E6T13xxx	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
369	Suzuki	Mitsubishi	E6T172	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
355	Suzuki	Mitsubishi	E6T900 M0	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
348	Suzuki / GM Group / Opel	IAW Marelli	MJD 602.04	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
254	Suzuki Outboard	Melco	MH7203F		TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
477	Suzuki Outboard	Melco	MH7202		TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		NO CHECKSUM
15	Tata	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E65
636	Tata	IAW Marelli	MJD 602	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E101
404	Tata Trucks (Cummins)	Motorola	CM876	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
722	Tigercat (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
13	Toyota	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
195	Toyota	Bosch	EDC17 CP07	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
356	Toyota	Bosch	ME7.9.5	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E97
54	Toyota	Bosch	ME7.9.51	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E97
746	Toyota	Denso	175822-773	76F0038AGD	TF010	36 - NEC NBD		E151
755	Toyota	Denso	175822-887	76F0038AGD	TF010	36 - NEC NBD		E151
752	Toyota	Denso	275036-1152	76F0039GD	TF010	36 - NEC NBD		E151
753	Toyota	Denso	275036-1152	76F0038AGD	TF010	36 - NEC NBD		E151
747	Toyota	Denso	275036-4820	76F0038AGD	TF010	36 - NEC NBD		E151
754	Toyota	Denso	275036-9170	76F0038AGD	TF010	36 - NEC NBD		E151
2	VAG (VW Group)	Bosch	EDC16 U2.1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	Patch (OBDDII Unlock)	E52
96	VAG (VW Group)	Bosch	EDC16+ CP	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	Patch (OBDDII Unlock)	E67
109	VAG (VW Group)	Bosch	EDC16+ CP	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	Patch (OBDDII Unlock)	E67
67	VAG (VW Group)	Bosch	EDC16+ U34	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	Patch (OBDDII Unlock)	E67
149	VAG (VW Group)	Bosch	EDC17 U01	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
207	VAG (VW Group)	Bosch	EDC17 U05 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
199	VAG (VW Group)	Bosch	EDC17C46	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDII Unlock)	E94
269	VAG (VW Group)	Bosch	EDC17C46	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	Patch (OBDDII Unlock)	E94
420	VAG (VW Group)	Bosch	EDC17C54	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
675	VAG (VW Group)	Bosch	EDC17C64	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
705	VAG (VW Group)	Bosch	EDC17C74	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
126	VAG (VW Group)	Bosch	EDC17CP04	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
425	VAG (VW Group)	Bosch	EDC17CP14	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	Patch (OBDDII Unlock)	E94
716	VAG (VW Group)	Bosch	EDC17CP14	TC1796	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG	Patch (OBDDII Unlock)	E94
146	VAG (VW Group)	Bosch	EDC17CP14 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDII Unlock)	E94
151	VAG (VW Group)	Bosch	EDC17CP14 internal flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDII Unlock)	E94
665	VAG (VW Group)	Bosch	EDC17CP14 TPROT7.0 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
166	VAG (VW Group)	Bosch	EDC17CP14 USA ext. flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDII Unlock)	E94
427	VAG (VW Group)	Bosch	EDC17CP20 (rom)	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
165	VAG (VW Group)	Bosch	EDC17CP20 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII	CHECKSUM MOD. / MOD. CHECKSUM
187	VAG (VW Group)	Bosch	EDC17CP20 internal flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
162	VAG (VW Group)	Bosch	EDC17CP24 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
203	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
268	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
676	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
739	VAG (VW Group)	Bosch	EDC17CP54	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
748	VAG (VW Group)	Bosch	EDC17CP74	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
50	VAG (VW Group)	Bosch	ME7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
51	VAG (VW Group)	Bosch	ME7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
52	VAG (VW Group)	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E84
539	VAG (VW Group)	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E84
48	VAG (VW Group)	Bosch	ME7.5	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
53	VAG (VW Group)	Bosch	ME7.5	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
49	VAG (VW Group)	Bosch	ME7.5.10	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
186	VAG (VW Group)	Bosch	ME7.5.20 - ME7.5.30	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E42
293	VAG (VW Group)	Bosch	MED17.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
723	VAG (VW Group)	Bosch	MED17.1	TC1796	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
168	VAG (VW Group)	Bosch	MED17.1 (rom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
218	VAG (VW Group)	Bosch	MED17.1 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
266	VAG (VW Group)	Bosch	MED17.1.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
707	VAG (VW Group)	Bosch	MED17.1.1	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
378	VAG (VW Group)	Bosch	MED17.1.6	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
690	VAG (VW Group)	Bosch	MED17.1.6	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
128	VAG (VW Group)	Bosch	MED17.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
472	VAG (VW Group)	Bosch	MED17.5	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
147	VAG (VW Group)	Bosch	MED17.5.1	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
267	VAG (VW Group)	Bosch	MED17.5.1	TC1766	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
435	VAG (VW Group)	Bosch	MED17.5.10	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
689	VAG (VW Group)	Bosch	MED17.5.2	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
334	VAG (VW Group)	Bosch	MED17.5.2 (rom)	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
179	VAG (VW Group)	Bosch	MED17.5.20	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
695	VAG (VW Group)	Bosch	MED17.5.21	TC1782	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
697	VAG (VW Group)	Bosch	MED17.5.24	TC1724	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
696	VAG (VW Group)	Bosch	MED17.5.5	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
715	VAG (VW Group)	Bosch	MED17.5.5	TC1762 / TC1766	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
358	VAG (VW Group)	Bosch	MED17.5.6	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
64	VAG (VW Group)	Bosch	MED9.1/MED9.5/MED9.5.10	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E58/E85
390	VAG (VW Group)	IAW Marelli	4AF	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
183	VAG (VW Group)	IAW Marelli	4AV	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
183	VAG (VW Group)	IAW Marelli	4BV	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
674	VAG (VW Group)	IAW Marelli	4CW	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
374	VAG (VW Group)	IAW Marelli	4GV	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
185	VAG (VW Group)	IAW Marelli	4HV	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
173	VAG (VW Group)	IAW Marelli	4TV	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
513	VAG (VW Group)	Siemens VDO	PCR2.1	ST95640	TF003	18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018)	Patch (OBDDII Unlock)	E131
75	VAG (VW Group)	Siemens VDO	SIMOS 5WP4 PPD1.x	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E69
174	VAG (VW Group)	Siemens VDO	SIMOS 6.2 6.3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E69
214	VAG (VW Group)	Siemens VDO	SIMOS 6.2 6.3	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E69
512	VAG (VW Group)	Siemens VDO	SIMOS 8.x	ST95640	TF003	18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018)	Patch (OBDDII Unlock)	E134
89	Valtra Sisu (AGCO Group)	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
342	Volkswagen Truck	Bosch	EDC16C8	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
58	Volkswagen Truck	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
93	Volkswagen Truck (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		NO CHECKSUM
68	Volvo	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
113	Volvo	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
158	Volvo	Bosch	EDC17CP22	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
681	Volvo	Bosch	EDC17CP48	TC1797	TF003	24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO		E94
743	Volvo	Bosch	EDC17CP68	TC1797	TF003	24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO		E94
624	Volvo	Bosch	ME7 (AM29F400)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
325	Volvo	Bosch	ME7 (AM29F800)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
626	Volvo	Bosch	ME7 (AM29F800)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
73	Volvo	Bosch	ME9+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E70
421	Volvo	Denso	079700-9xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)		NO CHECKSUM
326	Volvo	Denso	2.4	SH7058	TF005	07 - RENESAS SH7050 (TM007)		NO CHECKSUM
499	Volvo	Denso	HP.2	SH7055	TF005	07 - RENESAS SH7050 (TM007)		NO CHECKSUM
399	Volvo Penta	Bosch	EDC17CP22	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
357	Volvo Power Generator	TRW Motorola	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E80
138	Volvo Truck / Renault Truck	TRW Motorola	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E80
246	Volvo Truck / Renault Truck	TRW Motorola	EMS2 (EURO4/EURO5 version)	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)		E80
549	Volvo Truck / Volvo Penta	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E52
433	Weichai Truck (Weichai engines)	Bosch	EDC7 UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67
612	XCMG	Bosch	EDC7 U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)		E67/E133
559	Yale	Sagem	E3000	SH7055	TF005	07 - RENESAS SH7050 (TM007)		E73
562	Yamaha	Denso	13S-8591A-00 MICRO 1	SH7054	TF005	07 - RENESAS SH7050 (TM007)		E121
563	Yamaha	Denso	13S-8591A-00 MICRO 2	SH7054	TF005	07 - RENESAS SH7050 (TM007)		E121
646	Yamaha	Denso	1RC-8591A-XX	SH7058	TF005	07 - RENESAS SH7050 (TM007)		E121
574	Yamaha	Melco	F8T9487x	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
631	Yamaha	Mitsubishi	6D9-8591A-14	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
634	Yamaha	Mitsubishi	F8T81X	MH5XXXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
686	Yamaha	Mitsubishi	F8T820XXX	MH5XXXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
664	Yamaha	Mitsubishi	F8T84475	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
284	Yamaha	Mitsubishi	FX-SHO	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
656	Yanmar	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94